

APPENDIX C PHOTOGRAPHIC LOG



Photo 1: Pre-mobilization site conditions. View of future equipment storage and staging areas, facing southeast.



Photo 2: Site access road, equipment staging and R6 material stockpile area, facing west.

33-40011G\PRIN_WP\41967v2



Photo 3: R6 material stockpile on top of crushed stone pad at end of site access road, facing northeast.



Photo 4: R6 material placement via long-reach excavator, facing west.



Photo 5: R6 material placement via crane equipped with grapple attachment, facing northwest.



Photo 6: R6 material placement via crane, assisted by CEI spotter, facing east.



Photo 7: Extent of R6 material placement along southern sheetpile wall (Zone 1), facing east.



Photo 8: Site surveyor conducting upland survey of sheetpile wall targets, facing southwest.



Photo 9: Site surveyor conducting material placement survey, facing west.



Photo 10: Dock welders prepping for removal of old waler section, facing northeast.



Photo 11: Dock welders positioning new waler section already prepared for installation, facing northeast.



Photo 12: Dock welders continuing final fabrication and installation of HP8 segments, facing north.



Photo 13: View of repaired water section, HP8 segments, tie-rod extensions, and pack-outs, facing east.



Photo 14: New HP8 segments along sheetpile wall, facing west.



Photo 15: View of completed water repair area and HP8 segments, facing northwest.



Photo 16: Contractors performing tie-rod stress tests, facing southeast.



Photo 17: Installation of perimeter fencing along sheetpile wall, facing west.



Photo 18: View of completed perimeter fence, facing northeast.



Photo 19: Site restoration; removal of Reese mats which formed the site access road, facing east.



Photo 20: Site restoration; completed revegetation efforts (seeding) across disturbed areas of site, facing east.